

REMARKS**Status of the Claims**

Claims 1-35 are pending in the application. Claims 1-7, which were subject to a Restriction Requirement, have been canceled without prejudice to their being re-filed in a subsequent divisional application. Claims 8-35 stand rejected. Claims 8 and 25 have been amended. New claims 36-38 have been added. In view of the following remarks, applicants request re-examination and allowance of the claims.

Claims 8-35 are Patentable Over Taplan

Claims 8-11 stand rejected under 35 U.S.C. § 102 and claims 12-35 stand rejected under 35 U.S.C. § 103 over US Patent No. 6,032,662 to Taplan ("Taplan"). This rejection is respectfully traversed because Taplan does not anchor the supply tube to a burner box.

The cooktop of subject claims 8-24 has a burner box comprising:

"a force member acting against the burner box to bias at least a portion of the supply tube upwardly into the fuel feed port of the burner head a force member acting against the burner box to bias at least a portion of the supply tube upwardly into the fuel feed port of the burner head and anchor the supply tube to the burner box housing; "

(Independent Claim 8) Similarly, the cooking device of subject claims 25-35 has a burner box comprising:

"a force member acting against the burner box to bias at least a portion of the supply tube upwardly into the fuel feed port of the burner head and anchor the supply tube to the burner box housing; "

(Independent Claim 25). No corresponding feature is found in Taplan. Instead, Taplan pulls a burner box down against the upper surface of the cooktop or fixes the burner box to the cooktop and pushes a supply tube up against the bottom of the cooktop.

More specifically, in the embodiment of Fig. 1 of Taplan, spring 4 pulls burner box 9 down onto a top surface of cooktop 1. It does not anchor the supply tube to the burner box. This simply is different from the present claim requirement of a force member anchoring the supply tube to the burner box housing.

In Taplan's other embodiment, Figs. 2-4, supply tube 19 simply isn't anchored to a burner box. Spring 7 in Taplan's Figs. 2-4 embodiment sits on the housing and pushes supply tube 19 up against the bottom of the cooktop. This does not meet the present claim requirement of a force member anchoring the supply tube to the burner box housing.

Conclusion

In view of the forgoing, applicant requests that all claims pending in the application be allowed.

Respectfully submitted,

February 28, 2006



Gregory J. Cohan
Reg. No. 40,959
Customer No. 28316
Banner & Witcoff, Ltd.
28 State Street, 28th Floor
Boston, MA 02109
(617)-720-9600

U.S.S.N. 10/698,581
Page 9 of 9